Floyd Baumgardner
Ditch No. 2283
Henry - Jackson - Milton Liberty
Ditch Dook - 141 Wood Co.
Max Rothschild - Engineer

Nautting of bank on the east side - See X-Sections
All stumps and brush to be cut must be treated with stump and brush killer
If kill is not satisfactory a second application must be applied the next season