

On April 12 and 13,1976 I surveyed Iot 1273 Bowling Green, Ohio. I found the iron posts set on the southerly side of Lots 1276 to 1271 to be in error, the alley width was evidently omitted in figuring the width of Lot 1276 as a 11.3 foot surplus appears on Lot 1266, Post at north west corner of Lot 1273 encroaches 1.6 feet on the said Lot. Measurements taken on this Survey are marked "M." I advise using the area posts as they have been in place for over 26 years.

Reg. Sur. 890 14 Magnetic