

LAKE 808

SURVEY  
IN

S.E. 1/4, Sec. 35, T 7 N-R12 E, Lake Twp., Wo. Co. O  
L.W. Miller property.

Iron pins found at points shown thus ⊙  
Iron pipe set at points shown thus ○  
Fences shown thus ————  
Accepted existing ditch as West Line S.E. 1/4  
Nails set at points shown thus ⊗

Surveyed by H. Morgan  
July 1968 Reg. Sur. #90

Ohio Turnpike

Center Line ditch  
West Line S.E. 1/4

Carl Obrock  
property

10.10 ac.  
"C"

8.34 ac.  
"A"



Wayne  
Recker  
property

LAKE 808

473.4

S 62° 45' E

422.3

427.6

958.5

741.1  
751.1 S 0° 48' E

175.0

207.0

0.83 ac.  
"B"

N 89° 40'

9108