


582
MIDDLETON

SURVEYED
in
S.W. 1/4, Sec. 24, Middleton
Twp., Wood Co. O.

Control points shown thus ———— X
Wooden corner post shown thus ———— X
Iron pipe set at points shown thus —●—
Fences shown thus — X — X — X —

P/L P/L

E. Line of S.W. 1/4
accepted as being 6'
west of the west edge
of the existing pavement
on Pargillis Rd.



Surveyed by H. Morgan

Sept. 1964 Reg. Sur. 890

S. Line Sec. 24
Center Line s.R. 582 } S.E. Cor.

582
MIDDLETON