


521  
PLAIN

SURVEY

in

S.E. 1/4, Sec. 1, Plain Twp., Wood Co., O.  
Maurer Estate

Control points found at points shown thus  $\Delta$   
Iron pipe set at points shown thus  $\bullet$   
R.R. Spike set at point shown thus  $\times$



Simmons Rd.  
East Line S.E. 1/4 - Center U.S. 25

Surveyed by H. Morgan  
Apr. 1969 Reg. Sur. 890

A cerages shown in parentheses are actual.

521  
PLAIN