

580  
HENRY

SURVEY

in


S.E. 1/4, Sec. 25, Henry Township, Wood Co. O.

Control points shown thus  $\Delta$

Iron pipe set at points shown thus  $\odot$

R.R. Spike " " " " " "  $\oplus$

Limited Access Fence shown thus  $\times$ ----- $\times$



Surveyed by H. M. Moore  
July 1968 Reg. Sur. 890

580  
HENRY