

538  
MONTGOMERY



1181

# SURVEY

in  
S.E.  $\frac{1}{4}$ , Sec. 10, T 4 N R 12 E, Montgomery Twp.  
Wood Co. O.

538  
MONTGOMERY

King Haylett-Owner



Surveyed by H. Morgan  
Nov. 1968 Reg. Sur. 890

Control points are shown thus and are based on Ohio Dept. of Hwys. survey  $\Delta$   
P.K. Nail found at point shown thus  $\odot$   
" " set " " " "  $\times$

1181