

595
MIDDLETON


SURVEY
in
S.W. $\frac{1}{4}$ Sec. 32, T 6 N-R 11 E,
Middleton Twp. Wood Co. O.

Control points shown thus \odot
Nails set at points shown thus \times
Iron pipe set at points shown thus \circ

N.W. Cor.
S.W. $\frac{1}{4}$

Melvin Dierksheide--Owner

W. Line S.W. $\frac{1}{4}$
Mercer Rd.



Surveyed by H. Moran
July 1968 Reg. Sur. 890

595
MIDDLETON