

C.R.C.

C.R.C.

R.C.C.

C.R.C.  
P.O.M.

401  
Portage

Survey of Parcel 18  
in  
The Town of Mermill, Wo., Co., O.  
Dulaney Prop.

Iron pins found at points shown thus •

Iron pipe set " " " " O

Dimensions shown are measured unless marked R (Record)

Center line of the Dixie Hwy.  
West Line of Sec. 18, Portage Twp.


Liberty Twp.  
S.E. Cor. Sec. 13

Center Line of the Mermill Rd. (Ross Pike)

Sec. Line  
S.W. Cor. Sec. 18 - N.W. Cor. Sec. 19 Portage Twp.

In making the survey of Parcel 18 the only survey that I could find of the Town of Mermill was a survey made by Paul Dunipace in Sept. 1935 and on file in the office of the Wood County Auditor. The center line of the Ross Pike (now the Mermill Road) pavement is north of the center line shown on the Dunipace survey. As I could find nothing to disprove the Dunipace survey I accepted same as the basis of this Survey.

The said Parcel 18 is located in the S.W.  $\frac{1}{4}$  of Sec. 18 and the N.W.  $\frac{1}{4}$  of Sec. 19, Portage Twp.



Surveyed by H. M. M.

Jan. 1967 Reg. Sur. 890