S U R V E Y
in
Lot 60, Weston Ohio

Iron pipe set at points shown thus
P.K. Nails set at poinys shown thus



Note: Due to the absence of control points the center of existing pavements were accepted as the center lines of right of ways.

Surveyed by H M [illegible]
May 1977 Reg. Sur. 890

The face of the building located on Lot 7 checked as being on the northerly line of Locust Street. The northerly line of the said Street was established by producing the line of the said building easterly.