


408  
CENTER

S U R V E Y

in  
S.E. 1/4, Sec. 3, T 5 N-R 11, E., Center Township  
Wood Co., Ohio  
Emma L. Morris, Owner

Control points found at points shown thus  $\blacktriangle$   
Iron pipe set at points shown thus  $\circ$   
Railroad Spikes set at point shown thus  $\bullet$



Surveyed by H. Morgan  
Nov. 1972 Reg. Sur. 1890

408  
CENTER