


419
CENTER

SURVEY
in
west $\frac{1}{4}$, S.W. $\frac{1}{4}$, Sec. 29, Center Twp.
Wood Co. Ohio

Control points found at points shown thus Δ
Iron pipe set at points shown thus \odot
P.K. Nails set at points shown thus \times

Surveyed by H. M. ...
May 1977 Reg. Sur. 890



419
CENTER