


223
ROSSFORD

S U R V E Y
in
Lots 70 & 71, Rossford C.
Salomes Mierzewski Est.
Grantor



Iron pipe found at points shown thus ●
 Iron pipe set at points shown thus ○
 Fences shown thus —x—x—x—x—

- A { The east 53 feet of Lot 71 and the east 53 feet of the north 46.25 feet of Lot 70 Rossford, Ohio.
- B { The east 104.66 feet of Lot 71 and the east 104.66 feet of the north 46.25 feet of Lot ⁷⁰_A, Rossford Ohio less therefrom the east 53 feet.

Surveyed by H. Morgan

Apr. 1976 Reg. Sur. 890

223
ROSSFORD